CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Henry Meldrum under GLO contract No.450 and dated June 11, 1882.

Surveyor General records state:

Set post 4 ft long 4 in square 24 in in ground for Cor. to Secs. 2, 3, 10 & 11 marked T 2 S S 3 on NW, R 40 E S 10 on SW, S 11 on SE and S2 on NE with 5 notches on S and 2 on E edges from which:

A fir 36 in diam bears N45 $^{\rm O}$ E, 8 lks dist marked S2 BT. A fir 8 in diam bears N16 $^{\rm O}$ W, 18 lks dist marked T2SS3 BT. A fir 6 in diam bears S37 $^{\rm O}$ W, 34 lks dist marked R40ES10 BT. A tamarack 7 in diam bears S64 $^{\rm O}$ E, 7 lks dist marked S11 BT.

| E-17 | |
|---------|--------|
| DIAGRAM | |
| T 2 S | R 40 E |
| S 3 | S 2 |
| S 10 | S 11 |
| 1988 | |
| ORLS | 1639 |

Description of corner evidence found:

Searched 6 man-hours total on 11-19-87, 7-13-88 & 7-22-88 for original corner and accessories, declared lost to wildfire and logging.

UNION COUNTY SURVEYOR Date Received 9-22-88

File No. 136-88R

Date Filed

Description of monument and accessories I established to perpetuate the original location of this corner:

At position determined by double proportionate measurement between recovered controlling corners 1/2-mile North and 1-mile South, East and West...

Set $2\frac{1}{2}$ " aluminum cap on 2" aluminum pipe 24" in ground & 6" projecting out of ground with surrounding rock mound & 6' fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established: A red fir 10" diam brs N37 E, 68.5' dist mkd T2SR40ES2 BT. A ponderosa pine 7" diam brs S19 E, 96.3' dist mkd T2SR40ES11 BT.

A ponderosa pine 7 diam brs S01°W, 89.0' dist mkd T2SR40ES10 BT. A white fir 13" diam brs N51°W, 36.5' dist mkd T2SR40ES3 BT.

New BT's have a brass washer stamped PLS 1639 nailed to face of blaze. Attached signs 54-3 & 54-9 and painted face of blaze and 6" band of red around each BT.

Compass declination 190 East.

I hereby certify that the above described corner monument was properly reestablished by me and witnessed by Patti Hanley on August 5, 1988.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

Hanle

William L.

OREGON JULY 14, 1978 WILLIAM L. HANLEY 1639

| Office of County . Surveyor | . County ofUnion | |
|---------------------------------------|--|--|
| State of Oregon , I hereby certify ti | het the within instrument was filed in this office | |
| for record on the day of | , 19 | |
| by | | |
| (COUNTY OFFICIAL) | (DEPUTY) | |

Form R6-7100-57 (9/71)