

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

G 17


History of original corner establishment:

Corner established by Henry Meldrum under GLO contract No.450 and dated June 11, 1882.

Surveyor General records state:

Set post 3 ft long 3 ins square 24 ins in ground for 1/4 Sec. Cor. marked 1/4 S on W face from which:

A tamarack 8 ins diam bears S64°E, 86 lks dist marked 1/4S BT.
A fir 22 ins diam bears N31°W, 123 lks dist marked 1/4S BT.



Description of corner evidence found:

Searched 4 man-hours on 9-18-87 and 7-13-88 for original corner and accessories, declared lost to fire and logging - no trace of coner evidence found.

UNION COUNTY SURVEYOR
Date Received <u>9-22-88</u>
Date Filed <u>9-23-88</u>
By <u>G. LANGLITZ DEPUTY</u>
File No. <u>138-88 R</u>

Description of monument and accessories | established to perpetuate the original location of this corner:

At position midway between adjacent section corners North and South...

Set 2½" aluminum cap on 2" aluminum pipe 24" in ground & 6" projecting out of ground with surrounding rock mound & 6' fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established:

A white fir 9" diam brs N44°W, 17.2 ft dist marked 1/4S10 BT.

A western larch 8" diam brs N76°E, 15.3 ft dist marked 1/4S11 BT.

New BT's have a brass washer stamped PLS 1639 nailed to face of blaze. Attached signs 54-3 & 54-9 and painted face of blaze and 6" band of red around each BT.

Compass declination 19° East.

I hereby certify that the above described corner monument was properly reestablished by me and witnessed by Patti Hanley on August 5, 1988.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of.....County Surveyor..... County of.....Union.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)