


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

J-14

History of original corner establishment:

None. Corner established with this survey.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position midway between adjacement controlling corners 20 chains east & west...

Set a 2" x 30" aluminum pipe with 2½" aluminum cap 24" in ground & projecting 6" out of ground with surrounding earth mound & placed 6' steel fence post alongside with signs 54-2 & 54-9 attached. Cap marked as shown in corner diagram. No stones available for mound.

New bearing trees established:

White fir 13" dia brs N57°E, 29.5' dist mkd W 1/16 S 10 BT.

Western larch 17" dia brs S27½°E, 10.4' dist mkd W 1/16 S 15 BT.

New bearing trees have a brass washer marked PLS 1639 nailed flush to face of blaze. Attached signs 54-3 & 54-9 & painted face of blaze & a 6' band of red around each bearing tree.

Compass declination 19° East.

I hereby certify that the above described corner monument was properly established by me & witnessed by F.S. Munro on October 02, 1989.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of.....County Surveyor..... County of.....Union.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by.....
(COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

UNION COUNTY
SURVEYOR
(DEPUTY)
Date Received 3-12-90
Date Filed 3-12-90
By *Gregory T. Blackman*
File No. 13-90R

*GPO-591-971, 1988

J-14