

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:


Corner was originally established under GLO contract number No. 103, dated September 3rd, 1863, executed by David P. Thompson. Surveyor General field notes state:

Set post for quarter section corner in mound of Earth with charred, stake pits, as per instructions.

In 1889, J. W. Kimbrell notes using the corner as part of Old Book Surveys, Pages 144 & 145.

In 1899, Arthur Curtis notes, "Set quarter section corner, a marked stone 16"x10"x6" for corner" in Old Book Surveys, Page 346.

T 2 S R 40 E N-3



DESCRIPTION OF CORNER EVIDENCE FOUND:

No corner evidence found. Falls in the center of a drainage ditch ± 6 feet West of the North/South fence line. The area has been highly cultivated and drained.

SEE SURVEY NUMBER 037-2026

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by Survey I set a 2 ½"x30" aluminum pipe, 29" in the ground, with a 3" aluminum cap, marked as shown below, from which:


NEW BEARING OBJECTS:

A 5/8"x15" iron pin bears North 27°10 East, a distance of 8.85 feet, with a 1 ½" aluminum cap marked "BGB SURVEY MARKER NE RP".

A 5/8"x15" iron pin bears South 18°37 East, a distance of 11.74 feet, with a 1 ½" aluminum cap marked "BGB SURVEY MARKER SE RP".

A 5/8"x15" iron pin bears South 30°20 West, a distance of 10.25 feet, with a 1 ½" aluminum cap marked "BGB SURVEY MARKER SW RP".

A 5/8"x15" iron pin bears North 42°16 West, a distance of 8.77 feet, with a 1 ½" aluminum cap marked "BGB SURVEY MARKER NW RP".



Set steel fence post approx. 1 ft. West

I hereby certify that the corner was monumented on August 19th, 2026

Witness: Kyle Tucker, Emily McClelland



Renewal Date: June 30, 2028

I used a Leica GS 18 with RTK in the establishment of the new bearing objects. Basis of bearing is as per map of survey number 037-2026. Bearings and distances are measured to the center of the aluminum caps.

