USDA-FOREST SERVICE GPO 9	40-117				
File No. P-13	CORNER RECORD (S		o	Cor.	
T 28 R. YOE	//	County Union			
Meridالنظا		State Oregon	·		
CORNER DIAGRAM	Describe corner monument found Basalt Stone - 16" x 10" x 5" set 9 "above ground. Condition 01 I found no marks on the stone but I be lieve it to be the corner. (Later) I came post this stone again a believe I found chise! work on w face.				
 	DESCRIBE BEARING TREES OR O This stone is well set from which a large obout \$ 45°E, 80 ft and	3ft. South of we	Il made man	nd of stone che bears	
PHOTO IDENTIFICATION DATA Photo No.				~347.	
Filed At.	- Profesion of State of the			,	
Object IdentIdent. By	DESCRIBE CORNER LOCATION RE	LATIVE TO NEAR-BY FEAT	URES, ALSO HOW	TO REACH CORNER	
Signature					
PLANE COORDINATE POSITION DATA					
Stute Zone					
X				· · · · · · · · · · · · · · · · · · ·	
Y					
Estab. By					
	Division	Haadquarters	Date	FS-7100-52 (3/68)	

UNION COUNTY	
SURVEYOR	

Date Received

Date Filed 12-18-87

BYG. LANGCITZ, DEPM

File No. 2/6-87R

P-13

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner established by Henry Meldrum under GLO Contract number 450, dated June 11, 1882. Surveyor General record states:

Set Basalt stone 16x10x5 ins, 11 ins in ground for 1/4 Sec Cor marked 1/4 on W face and raised mound of stone alongside. Pits impracticable.

Union County monumentation record 216-87R calls finding a stone 16x10x5 ins set 9" above ground with possible chisel work on the West face.

Survey number 24-90 states the corner was searched for but not found.

No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found stone 16"x10"x5" set 9" above ground with mound of stone approximately 3 feet North. No chisel marks were identified on the stone, which had weathered considerably on the West face. Due to the well defined mound, the well set stone of called size, and the relativity to the adjacent corners, I accept this as being the original stone set by Meldrum.

See Survey Number 029-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position of the original corner stone, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with 2 $\frac{1}{2}$ " aluminum cap marked as shown below, 28" in the ground, from which:

NEW BEARING OBJECTS AND TREE:

A 5/8"x30" iron pin with aluminum cap marked UNION COUNTY SURVEYOR NE RP bears N 33°E, a distance of 12.06 feet, A 5/8"x30" iron pin with aluminum cap m

A 5/8"x30" iron pin with aluminum cap marked UNION COUNTY SURVEYOR SE RP bears S 45°E, a distance of 6.31 feet,
A 5/8"x30" iron pin with aluminum cap marked UNION COUNTY SURVEYOR SW RP

bears S 29°W, a distance of 7.22 feet,
A 28" diameter Ponderosa Pine bears N 25°W, a distance of 45.25 feet,
marked 1/4 S21 BT

Buried the original corner stone North and alongside monument. Raised a mound of stone around monument, 3 ft. base to top of cap. Set steel fence post approximately 2 feet North of monument.

Corner falls approximately 50 feet West of old North-South fence,

I hereby certify that the corner was

ed Wi

REGISTERED **PROFESSIONAL** LAND SURVEYOR

3 MM OREGON RICK G. ROBINSON 2219

Renewal Date December 31, 1998

on September 4, tness: Jeff Madsen

SURVEYOR COUNTY T 2 S R 40 E 1/4 S 21 S 22 1997 **OPLS 2219**

monument 1997.

T2S R40E P-13

22

S



Date Received 9-9-97

File Number <u>631 - 1997 R</u>

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distance to the bearing tree is to a 50d spike driven on the right side of the tree at the root crown. attached a brass washer marked OPLS 2219 to the BT blaze. The distances to the iron pins are to the center of the aluminum cap.