


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.



No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 029-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap marked as shown below, 40" in the ground (10" below ground surface), from which:

NEW BEARING TREE and OBJECT:

A 5/8"x30" iron pin with aluminum cap marked N RP bears N 55°E, a distance of 9.63 feet.

A 22" diameter triple bole tamarack bears S 3°E, a distance of 48.76 feet marked CW 1/16 S22 BT.

Position falls in fenced garden area.

Set steel fence post approximately 2 feet South of monument.

I hereby certify that the corner was monumented on September 8, 1997.


Witness: Jeff Madsen

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Rick G. Robinson

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date December 31, 1998



**UNION COUNTY
SURVEYOR**

Date Received 9-9-97

Date Filed 9-13-97

Filed By *Judy T. Blum*

File Number 028-1997R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distance to the bearing tree is to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze. The distance to the iron pin is to the center of the aluminum cap.