
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously established.



No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 029-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with 2 $\frac{1}{2}$ " aluminum cap marked as shown below, 28" in the ground, from which:

NEW BEARING TREES:

An 18" diameter White Fir bears N 22°E, a distance of 48.18 feet, marked C 1/4 S22 BT.

A 6" diameter White Fir bears S $85^{\circ}E$, a distance of 39.68 feet, marked X BT. An 18" diameter Tamarack bears S $56^{\circ}W$, a distance of 66.10 feet, marked C 1/4 S22 BT.

A 18" diameter Tamarack bears N 62°W, a distance of 40.38 feet, marked X BT.

Set steel fence post approximately 2 feet South of monument.

I hereby certify that the corner was monumented on September 5, 1997. Witnesses: Jeff Madsen and Greg Blackman, Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON

OREGON
July 17, 1986

RICK G. ROBINSON
2219


Beneval Date December 31, 1998

UNION COUNTY
SURVEYOR

Date Received 9-9-97

Date Filed 9-13-97

File Number 029 - 1997K



I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distance to the bearing trees is to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.