


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Henry Meldrum under GLO Contract no. 450 dated June 11, 1882, and his record states:

Set post 3 ft long 3 ins diam 24 ins in ground for 1/4 Sec.
Cor marked 1/4 S on W face. From which:

A fir 18 ins diam bears N80°E, 28 lks dist marked 1/4 S. B. T.
A fir 18 ins diam bears N78°W, 16 lks dist marked 1/4 S. B. T.



Description of corner evidence found:

None. Corner reestablished by proportionate measurement from survey control.
Corner position obliterated by Forest Service logging and road construction operations.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position midway between adjacent section corners north and south...

Set a 2" x 30" aluminum pipe with 2½" aluminum cap 24" in ground & projecting 6" out of ground with surrounding stone mound & placed 6' steel fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established:

Spruce 16" dia brs S86½°E, 78.8' dist mkd 1/4S24 BT.
Spruce 16" dia brs S18°W, 38.4' dist mkd 1/4S23 BT.

New bearing trees have a brass washer marked PLS 1639 nailed flush to face of blaze. Attached signs 54-3 & 54-9 and painted face of blaze and a 6" band of red around each bearing tree.

Compass declination 19° East.

I hereby certify that the above described corner monument was properly established by me & witnessed by F.S. Munro on October 02, 1989, 1989.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

William L. Hanley

OREGON
 JULY 14, 1978
 WILLIAM L. HANLEY
 1639

Office of.....County..Surveyor..... County of.....Union.....
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL)

**UNION COUNTY
SURVEYOR..**

(DEPUTY)

Date Received 3-12-90

Date Filed 3-12-90

By *Gregory J. Blackman*

File No. 20-90R