
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously established.



No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 029-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2  $\frac{1}{2}$ " x 30" aluminum pipe with 2  $\frac{1}{2}$ " aluminum cap marked as shown below, 20" in the ground, from which:

## NEW BEARING OBJECTS:

A 5/8"x30" iron pin with aluminum cap marked S22 RP bears N 61°E, a distance of 8.75 feet in small mound of stone. A 5/8"x30" iron pin with aluminum cap marked S27 RP bears S 53°E, a distance of 12.15 feet in small mound of stone.

Raised a mound of stone around monument, 3 ft. Base to top of cap. Set steel fence post approximately 2 feet South of monument.

I hereby certify that the corner was monumented on September 4, 1997. Witness: Jeff Madsen

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Wick G Muin
OREGON
July 17, 1996
RICK G. ROBINSON
2219

Renewal Date December 31, 1998

GRIFFITH & SIZE TO SIZ

UNION COUNTY
SURVEYOR

Date Received 9-9-97

Date Filed 9-13-97

Filed By 7.612 K

File Number 030-1997 R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distances are to the center of the aluminum cap.