


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established with this survey.

T-15



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by proper subdivision of section from survey control...

Set a 2" x 30" aluminum pipe with 2 1/2" aluminum cap 24" in ground & projecting 6" out of ground with surrounding stone mound & placed 6' steel fence post alongside with signs 54-2 & 54-9 attached. Cap marked as shown in corner diagram.

There being no trees available, the following bearing objects were established:

A basalt outcrop 24" x 24" projecting 24" out of ground brs S65° 45' E, 51.5' mkd B X O .

A basalt outcrop 40" x 21" projecting 12" out of ground brs N89° 30' E, 46.7' mkd B X O. Painted bearing objects red.

Compass declination 19° East.

I hereby certify that the above described corner monument was properly established by me & witnessed by F.S. Munro on September 30, 1989.

REGISTERED PROFESSIONAL LAND SURVEYOR

*William L. Hanley*

OREGON  
JULY 14, 1978  
WILLIAM L. HANLEY  
1639

Office of... County Surveyor..... County of... Union  
Oregon

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL)

<b>UNION COUNTY SURVEYOR</b>	
(DEPUTY)	
Date Received	<u>3-12-90</u>
Date Filed	<u>3-12-90</u>
By	<u><i>Gregory T. Blanton</i></u>
File No.	<u>26-90R</u>

\*GPO-591-971, 1988

T-15