


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established with this survey.

U-14



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by proper subdivision of section from survey control...

Set a 2" x 30" aluminum pipe with 2½" aluminum cap 24" in ground & projecting 6" out of ground with surrounding stone mound & placed 6' steel fence post alongside with signs 54-2 & 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established:

Ponderosa pine 20" dia brs S20°W, 43.0' dist mkd SW 1/16 S 27 BT.

Ponderosa pine 17" dia brs S70°W, 40.0' dist mkd SW 1/16 S 27 BT.

New bearing trees have a brass washer marked PLS 1639 nailed flush to face of blaze. Attached signs 54-3 & 54-9 & painted face of blaze & a 6' band of red around each bearing tree.

Compass declination 19° East.

I hereby certify that the above described corner monument was properly established by me & witnessed by F.S. Munro on September 30, 1989.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of..... County Surveyor..... County of..... Union.....
State of..... Oregon.....

I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by.....
(COUNTY OFFICIAL)

UNION COUNTY SURVEYOR	
(DEPUTY)	
Date Received	<u>3-12-90</u>
Date Filed	<u>3-12-90</u>
By	<u><i>Gregory T. Blackman</i></u>
File No.	<u>29-908</u>

GPO-591-971, 1988

U-14