


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

U-15

**History of original corner establishment:**

None. Corner established with this survey.



**Description of corner evidence found:**

None.

**Description of monument and accessories established to perpetuate the original location of this corner:**

At position established by proper subdivision of section from survey control...

Set a 2" x 30" aluminum pipe with 2 1/2" aluminum cap 24" in ground & projecting 6" out of ground with surrounding stone mound & placed 6' steel fence post alongside with signs 54-2 & 54-9 attached. Cap marked as shown in corner diagram.

**New bearing trees established:**

White fir 12" dia brs N53 1/2° E, 102.6' dist mkd CS 1/16 S 27 BT.  
Ponderosa pine 17" dia brs N10° W, 49.0' dist mkd CS 1/16 S 27 BT.

New bearing trees have a brass washer marked PLS 1639 nailed flush to face of blaze. Attached signs 54-3 & 54-9 & painted face of blaze & a 6' band of red around each bearing tree.

Compass declination 19° East.

I hereby certify that the above described corner monument was properly established by me & witnessed by F.S. Munro on September 30, 1989.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William L. Hanley*

OREGON  
JULY 14, 1978  
WILLIAM L. HANLEY  
1639

Office of..... County Surveyor..... County of..... Union  
State of..... Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....  
..... by .....  
(COUNTY OFFICIAL)

UNION COUNTY  
SURVEYOR  
(DEPUTY)  
Date Received 3-12-90  
Date Filed 3-12-90  
By Henry T. Blum  
File No. 30-90R

U-15