CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established with this survey.

V-14	
DIAGRAM	
T 2 S	R 40 E
$W \frac{1}{16}$	• S 27 S 34
1989	
ORL S	1639

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position midway between adjacent section corner W & adjacent 1/4 corner E...

Set a 2" x 30" aluminum pipe with $2\frac{1}{2}$ " aluminum cap 24" in ground & projecting 6" out of ground with surrounding stone mound & placed 6' steel fence post alongside with signs 54-2 & 54-9 attached. Cap marked as shown in corner diagram.

There being no trees available, the following bearing objects were established... A lava rock outcrop 6' x 6' projecting 4' out of ground brs S07 W, 78.1' dist mkd B X O.

A basalt boulder 36" x 28" projecting 8" out of ground brs $N27\frac{1}{2}^{\circ}E$, 47.0' dist mkd B X O. Bearing objects are painted red.

Compass declination 190 East.

I hereby certify that the above described corner monument was properly established by me & witnessed by F.S. Munro on September 30, 1989.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Harley
OREGON!
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of County Surveyor County of Uni	
for record on the day of	UNION COUNTY
Form R6-7100-57 (9/71)	Dato Received 3-12-90
	Date Filed 3-/2-90

•GPO-591-971, 1988

V-14