


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner ESTABLISHED by W. B. Barr under GLO Contract No. 355 dated June 14, 1880, and his record states:

Set stake 4 ft long 4 ins diam 18 ins in ground for 1/4 Sec. Corner. Raised mound of rock as per instructions.



Description of corner evidence found:

Found a 4" diam round wood post 30" long blazed on one face and faintly scribed 1/4 S lying in rock mound at foot of 15' high rock outcrop. This recovered wood post is lichen covered & heavily weather checked & accepted as original corner post.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position of rotten wood remains in center of rock mound...

Set a 2" x 30" aluminum pipe with 2 1/2" aluminum cap 24" in ground & projecting 6" out of ground with surrounding stone mound & placed 6' steel fence post alongside with signs 54-2 & 54-9 attached. Cap marked as shown in corner diagram. Original corner post painted red and placed alongside surrounding rock mound.

There being no trees available, the following bearing objects were established:

The face of a large basalt outcrop 15' high brs N26°W, 2.8' dist mkd B X O. A basalt rock outcrop 24" x 14" projecting 48" out of ground brs S70°E, 1.5' dist mkd B X O. Bearing objects painted with red paint.

Compass declination 19° East.

I hereby certify that the above described corner monument was properly established by me & witnessed by F.S. Munro on September 29, 1989.

REGISTERED PROFESSIONAL LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of... County Surveyor... County of... Union...
State of... Oregon... I hereby certify that the within instrument was filed in this office for record on the... day of... 19...
..... by
(COUNTY OFFICIAL)

UNION COUNTY
(DEPUTY SURVEYOR)

Date Received 3-12-90

Date Filed 3-12-90

By *Henry T. Blanton*

File No. 32-90R

*GPO-591-971, 1988

V-15