

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

V-23


History of original corner establishment:

Corner established by Henry Meldrum under GLO Contract no. 450 dated June 11, 1882, and his record states:

Set post 3 ft long 3 ins square 24 ins in ground for 1/4 Sec. Cor. marked 1/4 S on N face, from which:

A fir 7 ins diam bears N38°W, 12 lks dist marked 1/4 S BT.

A tamarack 14 ins diam bears S49°E, 41 lks dist marked 1/4 S BT.



Description of corner evidence found:

None. Corner reestablished by proportionate measurement from survey control.

Corner position has been burned many years ago.

Description of monument and accessories established to perpetuate the original location of this corner:

At position midway between adjacent section corners East & West...

Set a 2" x 30" aluminum pipe with 2½" aluminum cap 24" in ground & projecting 6" out of ground with surrounding earth mound & placed 6' steel fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram. No stones available for mound.

New bearing trees established:

Spruce 12" dia brs S40½°E, 16.0' dist mkd 1/4 S36 BT.

Spruce 12" dia brs N23°E, 53.5' dist mkd 1/4 S25 BT.

New bearing trees have a brass washer marked PLS 1639 nailed flush to face of blaze. Attached signs 54-3 & 54-9 & painted face of blaze & a 6' band of red around each bearing tree.

Compass declination 19° East.

I hereby certify that the above described corner monument was properly established by me & witnessed by F.S. Munro on September 17, 1989.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of... County Surveyor..... County of... Union.....
Oregon

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL)

UNION COUNTY (DEPUTY) SURVEYOR	
Date Received	<u>3-12-90</u>
Date Filed	<u>3-12-90</u>
By	<u><i>W. Black</i></u>
File No.	<u>34-90R</u>

GPO-591-971, 1988