History of original corner establishment:

Corner not set in original survey

B-21		
DIAGRAM		
T3N	R39E	
N 1/16		
\$2	S1	

No record of subsequent monumentation found in county records. Description of corner evidence found:

See map of survey No. 4-81

Description of monument and accessories I established to perpetuate the original location of this corner:

(COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

New 8Ts A 12" p pine bears \$ 780 marked N 1/16 A 20" p pine bears N 90 marked N 1/16	S1 BT W, 107.5 ft,	T3N R39E N 1/16 S2 S1
REGISTERED PROFESSIONAL LAND SURVEYOR OREGON JULY 10, 1964 DUANE I. GRIFFITH		Brass washer nailed to blaze. Used steel tape and magnetic compass will 17° East declination. Distance measured to center of tree.
644		URION COUNTY SURVEYOR
Office of	County of	Tot Romived

(DEPUTY)

File No. 124 - 83R