


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

P-17

History of original corner establishment:

Corner not set in original survey



No record of subsequent monumentation found in county records.

Description of corner evidence found:

See map of survey No. 4-81

Description of monument and accessories I established to perpetuate the original location of this corner:


At proportionate distance I set 2 1/2" x 30" iron pipe with brass cap marked as shown 26" in ground, from which:

NEW BTs

A 10" tamarack bears N 72° E, 35.6 ft, marked S 1/16 S2 BT

A 16" tamarack bears N 72° W, 9.2 ft, marked S 1/16 S3 BT

Raised mound of stone



Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 17° East declination. Distance measured to center of tree.

REGISTERED PROFESSIONAL LAND SURVEYOR

Handwritten signature of Duane I. Griffith

OREGON
JULY 10, 1984
DUANE I. GRIFFITH
644

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

Date Received _____
★ GPO—798-278

Date Filed _____

By _____

File No. 460-84 R