## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original comer establishment:
--

Corner was established by Frank W. Campbell in 1884 under GLO Contract No. 498, dated May 10, 1884. Surveyor General Record States:

Set post for 14 section corner from which:

- A fir  $8^{\prime\prime}$  diameter bears N 22 links A tamarack 20 $^{\prime\prime}$  diameter bears S  $6^{\circ}$  W, 25 links

E-19				
DIAGRAM T3N R39E				
\$ 2				
4				
s S 11				

No record of subsequent remonumentation found in county records. Description of corner evidence found:

Found SV BT--Found no evidence of other BT

See map of survey No. 4-81

Description of manument and accessories I established to perpetuate the original location of this corner:

At record Bearing and distance from BT I set $2^{\frac{1}{2}}$ x $30^{11}$ iron cap marked as shown $26^{11}$ in ground, from which:	n pipe with brass	
Original BT A 20" tamarack, dead and down bears S6°W, 16.5 ft, scribes visible	T3N R39E S 2	
	4	
New BTs A 15" white fir bears N 88° E, 28.6 ft, marked 4 S2 BT	s 11	
A 13" tamarack bears S 40° E, 42.1 ft, marked 4 S11 BT	1980 OPLS 991	



Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 17° East declination. Distance measured to center of tree.

UKION COUNTY

04,4			SUINAEAOR
Office of	County o	<i>f</i>	Det Received
State of 1 h		hin instrument was filed in t	nis office
for record on the day of		9	
(COUNTY OFFICIAL)	by	(DEPUTY)	By
5-7100-57 (9/71)		•	File No. 141-83R

Form R6-7100-57 (9/71)