


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

F-17A

History of original corner establishment:

Corner not set in original survey



No record of subsequent monumentation found in County Records.

Description of corner evidence found:

See map of survey No. 4-81


Description of monument and accessories established to perpetuate the original location of this corner:

At proportionate distance I set 2 1/2" x 30" iron pipe with brass cap marked as shown 23" in ground, from which:

New BTs

A 14" tamarack bears E, 48.5 ft, marked N 1/16 S11 BT

A 12" tamarack bears N 16° W, 26.6 ft, marked N 1/16 S10 BT



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 17° East declination. Distance measured to center of tree.

Office of..... County of.....
State of..... I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL)

(DEPUTY)

UNION COUNTY
SURVEYOR

Received _____
Date Filed _____
By _____
File No. 143-83R
K-100-799-274