


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

J-9

History of original corner establishment:



POST

8" SPRUCE N11W 15LKS MKD. T3N R39E S8 BT
 12" SPRUCE S40W 42LKS MKD. T3N R39E S17 BT
 12" SPRUCE S34E 12LKS MKD. T3N R39E S16 BT
 14" FIR N78E 20LKS MKD. T3N R39E S9 BT

Description of corner evidence found:

18" SPRUCE SNAG S40W 27.7' SCRIBING VISIBLE
 16" FIR SNAG S34E 7.9' SCRIBING VISIBLE
 16" DOWN FIR N78E 13.2' SCRIBING VISIBLE

Description of monument and accessories established to perpetuate the original location of this corner:

SET A 2"x30" IRON PIPE WITH A BRASS-CAP MARKED: T3N R39E
 S8 S9
 S17 S16
 1978
 RLS 346

10" FIR S78W 18.3' MKD. T3N R39E S17 BT
 24" FIR N42W 82.0' MKD. T3N R39E S8 BT
 12" FIR N43E 32.4' MKD. T3N R39E S9 BT
 12" FIR S70E 30.8' MKD. T3N R39E S16 BT

ALL BT'S HAVE A RED PAINTED STRIPE AND A BEARING TREE SIGN.
 THE NEW BT'S HAVE A BRASS WASHER STAMPED RLS 346 ON THE LOWER FACE.
 THERE IS A 6' STEEL FENCE POST ON LINE APX. 5' FROM THE CORNER.

A RED PAINTED AND BLAZED LINE RUNS NORTH AND SOUTH THROUGH THIS CORNER.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Wayne G. Harkin

OREGON
MAY 6, 1955
WAYNE G. HARKIN
346

Office of.....COUNTY SURVEYOR..... County of.....UNION.....
 State of.....OREGON.....

I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....

..... by
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY
SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 149-83R

★ GPO-798-276