## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No.J-17

# History of original corner establishment:

Corner established by F.W. Campbell under GLO contract No. 498 in May, 1884. Surveyor General's notes state: "Set basalt stone, 12X8X8 ins., 8 ins. in the ground, for cor. to secs. 10, 11, 14, and 15, marked with 4 notches on S. and 2 notches on E. edge; from which: A spruce, 20 ins. diam., bears N51°W, 20 lks dist. marked T3NR39ES10 BT. A spruce, 10 ins. in diam., bears N21°E, 40 lks. dist. marked T3NR39ES11 BT. A spruce, 10 ins. diam., bears S40°E, 20 lks. dist. marked

DIAGRAM	
T3N R39E	
S10   S11	
S15 S14	

T3NR39E S10 | S11

1980

T3NR39ES14 BT. A spruce, 30 ins. diam., bears S50°W, 25 lks. dist. marked T3NR39ES15

#### Description of corner evidence found:

Found 16 X 8 X 7 stone firmly set and marked with 4 notches on S and 2 notches on E. side. From shich: A 36" sown and rotten tree bears N52°W, 12.5 ft. A 24" W.F. snag bears N21°E, 28.0 ft. and a 48" W.F. snag bears S52°W, 16.3 ft. No trace of scribing as all the trees have grown over blazes and are rotten.

Corner falls east of a N-S fence and 200' south of creek.

# Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2 1/2" X 30" galvanized pipe and brass cap marked: Set S15 | S14 pipe 24" in the ground. No rock in the area. Placed mound OR PLS 1051 of stone at base of pipe. From which by magnetic declination of N20°E: A 24" white fir bears N52°E, 84.8 ft. scribed T3NR39ES11 BT. A 15" white fir bears \$87°W, 37.1 ft. scribed T3NR39ES15 BT. No other suitable trees. Painted blazes red and 6" red band around. Placed 54-3s and brass washers stamped PLS1051 on BTs. Placed 54-4 on steel fence post 5' south of the corner.

I herby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel T. Rowland Robert Boling

June 13, 1980

REGISTERED **PROFESSIONAL** LAND SURVEYOR

> OREGON OCT. 17, 1975 1051

Form

Office of County S  State of Oregon  for record on the 3.76	urveyor 	County of. certify that the with	Union in instrument was file .8.0	qu <b>ui: 01/20</b> 5A5A5A05 MUDH CONNA
(COUNTY C	FFICIAL	<i>DY</i>	(DEPUTY)	Date Received
R6-7100-57 (9/71)				Date Filed
				Ву

History of original corner establishment:

Corner was established by Frank W. Campbell, Contract No. 498. Commenced May, 1884, and completed May, 1884.

80.00 set a basalt stone 12 x 8 x 8 inches 8 inches in ground. 4 notches on South face and 2 notches on East face. From which:

A spruce 20 inches diameter bears N  $51^{\circ}_{0}$  W 20 lks. dist. A spruce 10 inches diameter bears N  $21^{\circ}_{0}$  E 40 lks. dist. A spruce 30 inches diameter bears S  $50^{\circ}_{0}$  W 25 lks. dist. A spruce 10 inches diameter bears S  $40^{\circ}_{0}$  E 27 lks. dist.

DIAGRAM T3N **239** E


No record of subsequent remonumentation found in County Records.

Description of corner evidence found:

Found stone and 3 possible BTs as marked by paint and location posters. No notches found on stone. BTs not notched, so no scribing visible.

Description of monument and accessories I established to perpetuate the original location of this corner:

No additional accessories set.



### CERTIFIED RECORD OF LAND CORNER MONUMENTATION

# HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner established by F.W. Campbell under GLO contract No. 498 dated March 10th, 1884. Surveyor General's field notes

Set basalt stone, 12x8x8 ins,. 8 ins. in the ground, for cor. to secs. 10,11,14, and 15, marked with 4 notches on S. And 2 notches on E. edge; from which:

A spruce, 20 ins. diam., bears N51°W, 20 lks dist. marked T3NR39ES10 BT.

A spruce, 10 ins. diam., bears N21°E 40 lks. dist. marked T3NR39ES11 BT.

A spruce, 10 ins. diam., bears S40°E, 20 lks. dist. marked T3NR39ES14 BT.

A spruce, 30 ins. diam., bears S50°W, 25 lks. dist. marked T3NR39ES15 BT.

In Survey Number 53-84, Barry Barbour brings the corner to county standard from original corner evidence. Union County Monumentation record 151-83R states: Found a 16x8x7 stone firmly set and marked with 4 notches on S and 2 notches on E. side, from which:

A 36" down and rotten tree bears N52°W, 12.5 ft.

A 24" White Fir snag bears N21°E, 28 ft. A 48" White Fir snag bears S52°W, 16.3 ft.

Set a 2 1/2" x 30" galvanized pipe and brass cap marked as shown below, 24" in the ground and placed a mound of stone at the base of pipe. From which:

A 24" White Fir bears N52°E, 84.8 ft. scribed T3NR39ES15 BT. A 15" White Fir bears S87°W, 37.1 ft. scribed T3NR39ES15 BT. Placed a steel fence post 5' South of corner.

#### DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 2 1/2" galvanized iron pipe, 4" above ground, with a 2 1/2" brass cap marked as shown below. From which:

A 30" White Fir bears North 52° East, a dist. of 84.80', alive and vigorous with scribes visible on partially healed blaze.

A 27" White Fir bears South 87° West, a dist. of 37.10', alive and vigorous with healed blaze.

A fence post 5' +/- South of monument.

See Survey Number 031-2021

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the iron pipe monument,

#### NEW BEARING OBJECTS:

An 8" White Fir bears South 86° East a dist. of 14.70' marked T3NR39ES14 BT

A 6" White Fir bears North 61° West a dist. 14.75' marked T3NR39ES10 BT


Corner falls approx. 150' South of Lookingglass Creek.


I hereby certify that the corner was perpetuated on June 18th, 2021.

Witness: Kyle A. Tucker

REGISTERED **PROFESSIONAL** LAND SURVEYOR REGON JEFFREY S. HSU 83571

Renewal Date: June 30, 2023





T3N R39EJ-17

11

S

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.