


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.

T 3 N R 39 E K-24



DESCRIPTION OF CORNER EVIDENCE FOUND:
None.

See Survey Number 056-2013

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position determined by survey, I set a 5/8" x 30" iron pin, 30 inches in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

An 8 inch Douglas Fir bears South 73° West, a distance of 95.30 feet, marked NE 1/16 S13 BT.
An 8 inch Ponderosa Pine bears North 23° West, a distance of 95.10 feet, marked NE 1/16 S13 BT.


Set a steel fencepost approximately 1 ft. North of corner monument.

I hereby certify that the corner was monumented on December 12, 2013.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Jeffrey S. Hsu
OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015



**UNION COUNTY
SURVEYOR**

Date Received 12/17/13

Date Filed 12/17/13

Filed By *WLG*

File Number 451-2013R

I used a steel tape and magnetic compass in the establishment of the accessories. Magnetic declination used was 16° East. Distances are to a 60d spike in the right hand side of the root crown of the trees. Bearings are to a brass washer marked OPLS 83571 in the BT blaze of the tree.