CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner monumented by F. W. Campbell in 1884 under contract No. 498, set a 10" X 8" X 8" basalt stone 8" in the ground, marked ¼ on West face. 6" diam. Spruce, East, 19 links, mkd. ¼SBT. 11" Diam. Spruce, S. 70° W., 21 links, mkd. ¼SBT.

<u>L-9</u>	
DIAGRAM T3N _M R39E S.17 S.16	

Description of corner evidence found:

10" X 8" X 8" stone with % scribe on West face, set firmly in place. Stump hole, East, 19 links. Stump hole, S. 70° W., 21 links.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2½" Diam. brass cap in a 2" X 30" iron pipe at the Corner and buried Cornerstone alongside pipe.

T3N R39E Cap stamped 14" D.B.H. Douglas Fir, S.5° W., 22.4', S 17 S 16 scribed 4S17BT. RPLS 1910 12" D.B.H. Tamarack, S. 72° E., 15.0', scribed %S16BT. 1982 Both B.T's. have brass washers marked RPLS 1910 between B&T, attention signs, B.T. tags, and red

painted bands. Steel fence post 4.0' North and South of Corner with attention, monument and property signs attached.

LAND SURVEYOR Marto OREGON CLAYTON-JESSE MARTIN 1910

REGISTERED **PROFESSIONAL**

		C.J. MARTIN SURVEYING 2751 JUNIPER ST
Office of SURVEYOR	County of UNION	UNION COUNT OR 97:86
State of	rtify that the within instrument was file	in this office
for record on the 29. day of OCTOR HOWARD L PERRY (COUNTY OFFICIAL)	by Jon Jones J. Deputy	Date Ruceived
Form R6-7100-57 (9/71)		Date Filed ☆ GPO—798-276
		File No. 155 - 83R