


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

T 3 N R 39 E L-22



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey Number 045-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


At position determined by survey, I set a 5/8" x 30" iron pin, with a 2 1/2" aluminum cap marked as shown below, 30 inches in the ground, from which:

A 7 inch Douglas Fir bears North 88° East, a distance of 4.00 feet, marked CW 1/16 S13 BT.
An 8 inch Douglas Fir bears North 16° West, a distance of 19.50 feet, marked CW 1/16 S13 BT.

I set a steel fencepost approximately 1 foot North of corner monument.

I hereby certify that the corner was monumented on September 24, 2013.

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

**UNION COUNTY
SURVEYOR**

Date Received 9/25/13
Date Filed 9/25/13
Filed By Neil G. Minner
File Number 431-2013R

BAGGETT - GRIFFITH & BLACKMAN

T3N R39E

W 1/16

C ————— C

S 13

2013

OPLS 83571

I used a steel tape and magnetic compass in the establishment of the bearing trees. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the tree. A brass washer marked OPLS 83571 is attached to the BT blaze of the bearing trees.