
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 3 N R 39 E M-20



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey Number 031-2021

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8"x30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

## NEW BEARING OBJECTS:

A 15" Ponderosa Pine bears South 1° West a dist. of 44.00' marked SE 1/16 S14 BT.

A 19" triple bole Ponderosa Pine bears North 42° West a dist. of 31.95' marked SE 1/16 S14 BT.

Set steel fencepost South approx. 1 ft.

I hereby certify that the corner was monumented on June 21, 2021.

Witness: Kyle A. Tucker, Emmitt A. Ambert

SE 1/16 S14

OPLS 83571
2021

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON June 2, 2010

JEFFREY S. HSU 83571

Renewal Date: June 30, 2023

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY
SURVEYOR

Date Received 7 15 2 1

Date Filed 7 15 2 1

File Number 077-702)

M-20