


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHMENT:**

Corner not previously established.

T 3 N R 39 E M-21



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None.

See Survey Number 045-2013

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position determined by survey, I set a 5/8" x 30" iron pin, with a 2 1/2" aluminum cap marked as shown below, 30 inches in the ground, from which:

- A 9 inch Douglas Fir bears South 20° East, a distance of 18.85 feet, marked S1/16 S13 BT.
- A 7 inch Douglas Fir bears South 31° West, a distance of 15.85 feet, marked S1/16 S14 BT.

I set a steel fencepost approximately 0.5 foot North of corner monument.  
I hereby certify that the corner was monumented on September 24, 2013.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR



OREGON  
June 2, 2010

JEFFREY S. HSU  
83571

Renewal Date: June 30, 2015

BAGETT - GRIFFITH & BLACKMAN

T3N R39E

S 1/16

S 14 | S 13

2013

OPLS 83571

UNION COUNTY  
SURVEYOR

Date Received 9/25/13

Date Filed 9/25/13

Filed By M.G. Min

File Number 433-2013R

I used a steel tape and magnetic compass in the establishment of the bearing trees. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the tree. A brass washer marked OPLS 83571 is attached to the BT blaze of the bearing trees.