


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

T 3 N R 39 E M-22



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey Number 045-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, with a 2 1/2" aluminum cap marked as shown below, 30 inches in the ground, from which:


A 5/8"x30" iron pin bears North 29° East, a distance of 50.33 feet, with a 1 1/2" aluminum cap marked NERP. Pin falls on the West side of a railroad tie fence corner.

A 5/8"x30" iron pin bears South 61° East, a distance of 26.88 feet, with a 1 1/2" aluminum cap marked SERP. Pin falls on the Westerly side of an North/South running fenceline.

I set a steel fencepost approximately 1 foot North of corner monument.

I hereby certify that the corner was monumented on September 24, 2013.

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

UNION COUNTY
SURVEYOR

Date Received 9/25/13
Date Filed 9/25/13
Filed By [Signature]
File Number 432-2013R

BAGETT - GRIFFITH & BLACKMAN

T3N R39E

SW 1/16 S13

2013

OPLS 83571

I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination. Bearings and distances are to center of the aluminum cap.