


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

T 3 N R 39 E M-24



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey Number 056-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 30 inches in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

A 5/8"x30" iron pin bears North, a distance of 20.00 feet, with a 1 1/2" aluminum cap marked BGB SURVEY MARKER N RP.

A 5/8"x30" iron pin bears East, a distance of 19.85 feet, with a 1 1/2" aluminum cap marked BGB SURVEY MARKER E RP.

Set a steel fencepost approximately 0.5 feet North of corner monument. Corner falls in an open meadow.

I hereby certify that the corner was monumented on December 13, 2013.

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

BAGETT - GRIFFITH & BLACKMAN

T3N R39E

SE 1/16 S13


2013

OPLS 83571

UNION COUNTY
SURVEYOR

Date Received 12/17/13

Date Filed 12/17/13

Filed By 

File Number 454-2013R

I used a Leica RTK GPS in the establishment of the bearing accessories. Basis of bearing is as per Survey Number 056-2013. Bearings and distances are to the center of the aluminum cap.