## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner established by Frank W. Campbell under GLO Contract Number 498, dated March 10th, 1884.


Surveyor General Field Notes state:

Set a pine post 3 ft long 3 ins square 24 ins in the ground for 1/4 sec corner marked 1/4 S on N face

from which:

A fir 6 ins diam bears S6°W 28 lks dist marked 1/4 S B.T

A fir 6 ins diam bears N20°W 40 lks dist marked 1/4 S B.T



## DESCRIPTION OF CORNER EVIDENCE FOUND:

None. Area has been historically logged extensively.

SEE SURVEY NUMBER 025-2023

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a 2 1/2" x 30" aluminum pipe, 26" in the ground, with 3" aluminum cap marked as shown below, from which:

## NEW BEARING OBJECTS:

A 16" diam. Ponderosa Pine bears North 74° East, a

dist. of 12.20 feet, marked 1/4 S15 BT A 14" diam. Ponderosa Pine bears South 42° East, a

dist. of 11.10 feet, marked 1/4 S22 BT


A 14" diam. Ponderosa Pine bears South 74° West, a

dist. of 6.10 feet, marked 1/4 S22 BT

A 12" diam. Western Larch bears North 17° West, a

dist. of 15.90 feet, marked 1/4 S15 BT

Set steel fence post approx. 1 foot West I hereby certify that the corner was monumented on September 30, 2023.



REGISTERED **PROFESSIONAL** LAND SKIRVEYOR

OREGON JEFFREY S. HSU 83571

Renewal Date: June 30, 2025

I used a tape and compass in the establishment of the new accessories. Bearing is measured to a brass washer labeled OPLS 83571 located at the center of BT blaze, with a declination of 14° East. Distance is measured to a 60d spike nailed to the right side base of tree.

UNION COUNTY **SURVEYOR** 

Date Received 10/18/23

File Number <u>055-2023R</u>

N - 15