


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 3 N R 39 E Q-19



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 038-2016

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown below, 30 inches in the ground, from which:


NEW BEARING TREES:

A 9" Ponderosa Pine bears South 69° East, a distance of 24.40 feet, marked CS 1/16 S23 BT.
A 9" Douglas Fir bears North 36° West, a distance of 19.95 feet, marked CS 1/16 S23 BT.

I hereby certify that this monument was set November 29, 2016. Corner falls on N side of a logging road approx. 24 feet South of an East/West running fenceline. A fence corner bears North 46° East, 25 feet. Set a steel fencepost approx. 3 ft. North of corner monument.



Renewal Date: June 30, 2017



UNION COUNTY SURVEYOR

Date Received 11/30/16

Date Filed 11/30/16

Filed By [Signature]

File Number 048-2016R

I use a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 15° East. Distances are to a spike in the root crown of the trees.