


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 3 N R 39 E S-16



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 066-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown below, 30 inches in the ground, from which:

NEW BEARING TREES:

A 14" Ponderosa Pine bears North 19° East, a distance of 33.65 feet, marked NE 1/16 S27 BT.
A 8" double boled Douglas Fir bears North 13° West, a distance of 60.70 feet, marked NE 1/16 S27 BT (scribe on East trunk)

Set a steel fencepost approximately 1 foot East of the corner monument. Corner falls on the East side of a logging road.

I hereby certify that the corner was monumented November 19, 2015.


UNION COUNTY SURVEYOR

Date Received 11/20/15

Date Filed 11/20/15

Filed By [Signature]

File Number 173-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 15° East. Bearings are to a brass washer marked OPLS 83571 in the lower BT blaze. Distances are to at 60d spike in the right hand side of the tree.