


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner not previously established.

T 3 N R 39 E T-16



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None.

SEE SURVEY NUMBER 066-2015

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown below, 27 inches in the ground, from which:

**NEW BEARING TREES:**

A 12" Douglas Fir bears South 22° West, a distance of 16.00 feet, marked CE 1/16 S27 BT.  
An 8" Ponderosa Pine bears North 18° West, a distance of 43.10 feet, marked CE 1/16 S27 BT.

Set a steel fencepost approximately 1 foot North of the corner monument. Corner falls approximately 20 feet West of a North/South running fenceline.

I hereby certify that the corner was monumented November 12, 2015.


**UNION COUNTY SURVEYOR**

Date Received 11/20/15

Date Filed 11/20/15

Filed By [Signature]

File Number 176-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 15° East. Bearings are to a brass washer marked OPLS 83571 in the lower BT blaze. Distances are to at 60d spike in the right hand side of the tree.