


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner not previously established.

T 3 N R 39 E U-17



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None.

SEE SURVEY NUMBER 066-2015

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown below, 30 inches in the ground, from which:

**NEW BEARING TREES:**


A 9" Douglas Fir bears South 60° East, a distance of 30.35 feet, marked S 1/16 S26 BT.

A 9" Ponderosa Pine bears North 86° West, a distance of 69.95 feet, marked S 1/16 S27 BT.

Corner falls approximately 25 feet East of a fence corner.

I hereby certify that the corner was monumented November 13, 2015.

<b>UNION COUNTY SURVEYOR</b>	
Date Received	11/20/15
Date Filed	11/20/15
Filed By	<i>W. G. K...</i>
File Number	179-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR
<i>Jeffrey S. Hsu</i>
OREGON June 2, 2010
JEFFREY S. HSU 83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 15° East. Bearings are to a brass washer marked OPLS 83571 in the lower BT blaze. Distances are to at 60d spike in the right hand side of the tree.