


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by F.W. Campbell under GLO contract no. 498, dated May 30, 1884. Surveyor General field notes state:

- A fir, 20 in. diam. which I mark 1/4 S on N face for 1/4 Sec corner, from which:
- A fir, 8 in. diam. bears N20°E, 19 lks. dist. marked 1/4 S BT.
- A fir 8 in. diam. bears South, 20 lks. dist. marked 1/4 S BT.

T 3 N R 39 E V-15



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 066-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap, marked as shown below, 27 inches in the ground, in a collar of stone 1 ft. diam., from which:

NEW BEARING TREES:

- A 7" White Fir bears North 37° East, a distance of 9.95 feet, marked 1/4 S27 BT.
- A 12" Douglas Fir bears South 80° East, a distance of 17.20 feet, marked 1/4 S34 BT.
- A 10" White Fir bears South 80° West, a distance of 16.85 feet, marked 1/4 S34 BT.
- An 11" Spruce bears North 63° West, a distance of 47.95 feet, marked 1/4 S27 BT.

Set a steel fencepost approximately 1 foot North of corner monument.
I hereby certify that the corner was monumented November 11, 2015.


UNION COUNTY SURVEYOR

Date Received 11/20/15

Date Filed 11/20/15

Filed By WLG/MLM

File Number 181-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 15° East. Bearings are to a brass washer marked OPLS 83571 in the lower BT blaze. Distances are to at 60d spike in the right hand side of the tree.