


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by F.W. Campbell under GLO contract no. 498, dated May 30, 1884. Surveyor General field notes state:

Set fir post 3 ft. long, 3 in. square, 24 ins. in the ground for 1/4 Sec. corner marked 1/4 S on W. face, from which:
A fir, 10 in. diam., bears N85°W, 27 lks. dist. marked 1/4 S BT.
A fir, 20 in. diam., bears S88°E, 46 lks. dist. marked 1/4 S BT.

T 3 N R 39 E X-13



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 066-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


At proportionate position, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap, marked as shown below, 25 inches in the ground, in a collar of stone 1 ft. diam., from which:

NEW BEARING TREES:

An 8" White Fir bears North 67° East, a distance of 42.65 feet, marked 1/4 S34 BT.
An 11" Ponderosa Pine bears South 47° East, a distance of 47.30 feet, marked 1/4 S34 BT.
A 14" Douglas Fir bears South 68° West, a distance of 18.15 feet, marked 1/4 S33 BT.
A 7" White Fir bears North 35° West, a distance of 31.35 feet, marked 1/4 S33 BT.

I hereby certify that the corner was monumented November 11, 2015.

UNION COUNTY SURVEYOR
Date Received 11/20/15
Date Filed 11/20/15
Filed By [Signature]
File Number 184-2015R



REGISTERED PROFESSIONAL LAND SURVEYOR
[Signature]
OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 15° East. Bearings are to a brass washer marked OPLS 83571 in the lower BT blaze. Distances are to at 60d spike in the right hand side of the tree.