


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 3 N R 39 E X-15



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 069-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap, marked as shown below, 29 inches in the ground, from which:

NEW BEARING TREES:

- A 5 inch Douglas Fir bears North 54° East, a distance of 8.35 feet, marked C1/4 S34 BT.
- A 7 inch White Fir bears South 45° East, a distance of 16.65 feet, marked C1/4 S34 BT.
- A 13 inch Ponderosa Pine bears South 26° West, a distance of 57.15 feet, marked C1/4 S34 BT.
- A 5 inch Western Larch bears North 45° West, a distance of 20.40 feet, marked C1/4 S34 BT

Set a steel fencepost approximately 0.5 feet North of corner monument. Corner falls approximately 18 feet South of an East/West running fence.

I hereby certify that the corner was monumented December 14, 2015.


**UNION COUNTY
SURVEYOR**

Date Received 12/16/15

Date Filed 12/16/15

Filed By [Signature]

File Number 187-2015R



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

[Signature]

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 15° East. Bearings are to a brass washer marked OPLS 83571 in the lower BT blaze. Distances are to at 60d spike in the right hand side of the tree.