


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 3 N R 39 E Y-16



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 069-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown below, 32 inches in the ground, from which:

NEW BEARING TREES:

A 19 inch Ponderosa Pine bears North 33° East, a distance of 21.50 feet, marked SE 1/16 S34 BT. Tree is in an East/West running wire fence.

A 14 inch Ponderosa Pine bears North 49° West, a distance of 43.80 feet, marked SE 1/16 S34 BT.

Set a steel fencepost 15 feet North of corner monument. Corner falls on the Northwesterly side of a right angle bend in Keen Cabin Creek Road. Road bears East and South.

I hereby certify that the corner was monumented December 14, 2015.


**UNION COUNTY
SURVEYOR**

Date Received 12/16/15

Date Filed 12/16/15

Filed By [Signature]

File Number 189-2015 R



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

[Signature]

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 15° East. Bearings are to a brass washer marked OPLS 83571 in the lower BT blaze. Distances are to at 60d spike in the right hand side of the tree.