


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. ^A ~~X~~-3

History of original corner establishment:

Corner established by Frank W. Campbell under G.L.O. Contract #507 in August, 1884. Surveyor's General's notes state: "Set a Tamarac post 3 ft. long 3 ins. square 18 ins. in the ground for 1/4 Sec. corner marked 1/4 S. on N. face from which: A Tamarac 13 in. diam. bears S13°W, 19lks. dist. marked 1/4 S.B.T.. A Tamarac 18 ins. diam. bears N13°E 21lks. dist. marked 1/4 S.B.T."



Description of corner evidence found:


Found point with decomposed wood.

From which: A Tamarac 20" in dia. bears S16°W, 13.1 feet, scribed 1/4S. A Tamarac 24" in dia. bears N15°E, 14.6 feet, no scribing visible and inside is rotten.

SW BT is dead.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 26" in the ground.



No rock in the area.

From which: A Fir 9" in dia. bears N02°E, 20.2 feet, scribed 1/4S31BT. A Fir 8" in dia. bears S10°E, 16.9 feet, scribed 1/4S6BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-4 on steel fence post 5' East of corner. Placed 54-5 on tree 10' West of corner. Placed 54-5 on road 225' East of corner.

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers Dan T. Rowland

September 26, 1978

REGISTERED PROFESSIONAL LAND SURVEYOR

Barry B. Barbour OREGON OCT. 17, 1973 BARRY B. BARBOUR 1051

Office of...County Surveyor... County of... Union... State of... Oregon... hereby certify that the within instrument was filed in this office for record on the...20... day of... November... 1978

(COUNTY OFFICIAL) by (DEPUTY)

UNION COUNTY SURVEYOR Date Received 9/29/78 Date Filed By File No. 178-83R