CERTIFIED RECORD OF LAND CORNER MONUMENTATION

DIAGRAM

S.34

S.3

R40E

R40E

S.35

S.2

T4N

T3N

T4N R40E

T3N R40E

ORLS 506

1973

S.3

S.34 | S.35

S.2

History of original corner establishment:

Corner established in 1884 by Herman D. Gradon, under contract No 517 with the General Land Office.

Surveyor General records state: Set post, 4" square marked: T4N S.35 in NE, T3N S.2 on SE, R40E S.3 on SW,S.34 on NW faces with 2 notches on E. and 4 notches on W. edges. From which

A fir,18" diam. bears N.24°E., 40 links dist. marked T4N R40E S.35 BT

A pine, 30" diam. bears S.20°E., 34 links dist. marked T3N R40E S.2 BT

A fir, 20" diam. bears S.16°W., 37 links dist. marked T3N R40E S.3 BT

A fir,20" diam. bears N.65°.W.,9 links dist,mkd:T4N R40E S.34 BT

Description of corner evidence found:

At the assumed corner there was no post in evidence. original bearing trees:

A fir stump, scribing on fallen snag, now 20" diam. in the NE Quadrant A pine snag, all scribing visible, now 30" diam. in the SE Quadrant

Description of monument and accessories I established to perpetuate the

original location of this corner As the evidence found agrees with the original GLO records, I reversed the bearings and distances from the found BTs and set a l" galvanized iron pipe with a 23" brass cap marked from which: (new BTs)

A fir, 7" diam. bears N.67°E.,17.8 feet dist. marked T4N R40E S.35 BT

A fir, 8" diam. bears S.45°E., 35.1 feet dist. marked T3N R4CE S.2 BT

A fir, 9" diam. bears S.49°W.,29.3 feet dist. marked T3N R4OE S.3 BT

A fir, 5" diam. bears N.73°W., 2.9 feet dist

marked T4N R40E S.34 BT Note: I plazed USFS bearing tree signs on the 4 new BTs along with a brass washer stamped ORLS 506 in the lower blaze.

REGISTERED PROFESSIONAL LAND SURVEYOR mblon OREGON
MAY 13, 1960
RALPH P. THOMPSON
506

for record on the 2.7. day of	June , 1973 , at .	,
(COUNTY OFFICIAL)		PUTY) SURVEYOR
		Date Received
		Date Filed
		Ву
rm R6-7100-57 (9/66)		File No. 181-83R