CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

A post 3 ft. long, 3 ins. sq., 24 ins. in the ground.

34 ins. Pine S 21° E 60 lks. marked $\frac{1}{4}$ S BT 24 ins. Pine S 54° W 73 lks. marked $\frac{1}{4}$ S BT

C-/
DIAGRAM
R39E R40E
S1 S6

Description of corner evidence found:

36" Pine S11E 40.4° (old BT)
12" Fir N44W 23.7° (new BT)

Iron pipe with Brass-Cap marked

T3N R39E R40E S1 S6 1977 RLS 1097

Description of monument and accessories I established to perpetuate the original location of this corner:

All BT's have a red painted stripe and BT tags. The new BT's have a brass washer stamped RLS 346 nailed to the lower blaze. There is a 6° steel fence post within 5° of the corner.


There is a red painted and blazed line running North and South through this corner.

OREGON
MAY 6, 1925
WAYNE O. HARRIS

Office of OREGON , I hereby certify that the within instrument was filed in this office.

for record on the...... day of....... , 19....

Form R6-7100-57 (9/71)



REGISTERED PROFESSIONAL

SURVEYOR

History of original corner establishment:

Corner was established by Rufus S. Moore, Contract No. 437, Commenced July, 1882, and completed August, 1883.

40.00 set a post 3 feet long 3 inches diameter 24 inches in ground for $\frac{1}{4}$ corner.

From which:

A pine 34 inches diameter bears S 21° E 60 lks. dist. A pine 24 inches diameter bears S 54° W 73 lks. dist.

DIAGRAM
TON
239E ELOE
VA CORNER

Description of corner evidence found:

Found a pine scribed "1" S 21° E 60 lks. dist.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2" \times 30" iron pipe 15 inches in ground with brass cap marked as shown. Raised a stone mound around pipe. Established a scribed BT:

A fir il inches diameter bears N 44° W 27.3 ft. dist.

		T3N
1	UNION COUNTY	14 CORNER
	Date Received	. 1 06
• 1	Date Filed	C. 1977
	By	J. Joseph