


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-17

History of original corner establishment:

Corner established by H. D. Graden, under G.L.O. contract No. 517, in November, 1884. Surveyors General's notes state: "Set a post 3 ft. long, 3 ins. square, 24 ins. in the ground, for 1/4 sec. corner, marked 1/4S on W. face; from which: A fir, 18 ins. in diam. bears N89°E, 30 lks. dist. marked 1/4S BT. A tamarac 24 ins. diam., bears S40°W, 20 lks. dist. marked 1/4S BT."



Description of corner evidence found:

No trace of wood post could be found. Found 22" fir snag, N89°E, 19.8 ft., scribed "4S". Found 26" tamarac snag, S31°W, 13.2 ft., scribed "1/4S". Trees have 54-3s and location tags.

Description of monument and accessories I established to perpetuate the original location of this corner:

At center of above described point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground. No rock in the area.

From which: A 22" white fir bears N57°E, 52.6 ft. scribed 1/4 S2 BT. An 18" white fir bears N60°W, 28.7 ft. scribed 1/4 S3 BT. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Painted blazes red and 6" red band around. Placed 54-4 on steel fence post 5' North of corner. Placed 54-5 on a 5" fir, 5' West of corner.

T3NR40E
1/4

S3 + S2

OR PLS 1051
1979

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour
OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers.
Robert Stevens
Ray McVey
July 13, 1979

Office of..... County Surveyor County of..... Union
Oregon
State of..... I hereby certify that the within instrument was filed in the office of the
for record on the 26 day of July 1979
..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received _____
Date Filed _____ GPO 799-509
By _____
File No. 187-83R