## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-11

History of original corner establishment:

Corner established in November, 1884 by H.D. Gradon under G.L.O. Contract #517. Surveyor's General's notes state: "A Spruce 8 ins. in diam. which I marked 1/4 S on N face for 1/4 Sec. corner, from which: A Spruce 8 ins. in diam bears N20 E, 31ks. dist marked 1/4 S.B.T.. A Spruce 6 ins. in diam. bears S50 E, 121ks. dist marked 1/4 S.B.T."

DIAGRAM	
T3N R40E	
1/1 S4	
1/4 s9	

Description of corner evidence found:

Found 8" down tree scribed 1/4S and rotton stump with hole at foot of tree, from which: A 10" Spruce snag bears N35 E, 2.0 feet.

Broken part of snag on ground reads "45".

Description of monument and accessories lestablished to perpetuate the original location of this corner: (At stump hole) Set  $2\frac{1}{2}$ " x 30" galvanized pipe with brass cap marked: Set pipe 25" in the ground.

T3N R40E S4 1/4 <del>S9</del> OR PLS 1051 1978

No rock in the area.

From which: A Fir 16" in dia. bears N10°E, 62.8 feet, scribed 1/4S4BT. A Fir 11" in dia. bears S60°W, 80.9 feet, scribed 1/4S9BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-4 on steel fence post 5' West of corner. Placed 54-5 on tree 30' West of corner. Marked 54-3 on snag and set down corner tree against snag and painted scribing red. Corner is on North side of East-West fence.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1 0 5 1

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses:

David L. Landers Dan T. Rowland

October 13, 1978

Office of County Surveyor  State of Oregon thereby certify the for record on the .20 day of . November	it the within instrument was filed in this office COUNTY
Form R6-7100-57 (9/71)	Date Received  Date Filed  'Y GPO 799-509
	By

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

mistory or original corner establishment:	index: E-II
Corner established in 1884 by Gradon. His note A Spruce 8 ins. in diam. which I marked 1/4S of face for 1/4 sec. corner, from which: A spruce 9 ins. in diam. bears N20°E, 3 lks. of marked 1/4S BT. A Spruce 6 ins. diam. bears S5 12 lks. dist. marked 1/4S BT.	on N
In 1978, PLS 1051 remonumented this corner. His record reads: Found 8" down tree scribed 1/4 S and rotten sthole at foot of tree, from which: A 10" Spruce snag bears N35°E, 2.0 feet. Broke reads 4S. Set 2 1/2 " x 30" galvanized pipe with brass of Set pipe 25" in ground. No rock in the area. F	11 en part of snag on ground :ap marked: (see diagram)
A Fir 16" in dia. bears N10°E, 62.8 feet, scri A Fir 11" in dia. bears S60°W, 80.9 feet, scri	bed 1/4 S4 BT. bed 1/4 S9 BT.
Found the iron pipe as described with brass cadiagram. From this monument: A 33" dbh White Fir, N8°44'E, 83.2', with heal A 15" dbh White Fir, S56°46'W, 81.2', with hea	ed blaze.
Description of monument and accessories I esta original location of this corner:	ablished to perpetuate the
The bearings were based on the recorded bearing to the east and this quarter corner as recorded Union County survey 73-79. I set the following A 7" dbh Ponderosa Pine bears N41°19'W, 10.8' A 7" dbh Engleman Spruce bears S54°02'E, 28.6' An aluminum washer stamped RLS 852 is nailed be on the new trees. All four trees have LSM and Painted 6" red bands around all four trees and blazes red.	ed by PLS 1051 in new witness trees: scribed 1/4 S4 BT; scribed 1/4 S9 BT. etween the letters B and T BT signs attached.
This work was done August 7, 1992.  PROSES LAND SU  David L. H.	SIONAL DRVEYOR
OREC JULY 18 DAVID L. 18	2. 1968 HADDOCK
Office ofCounty of State of, I hereby certify that the	
the child diffus for record on theday	within instrument was filed of, 19
БУ	DEPUTY )
Form R6-7100-57 (9/71)	

Data Received 9/28/52
Data Filed 10/2/92
By Ly A 7- Blace
File No. 07/-1992