


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-17

History of original corner establishment:

Corner established by H. D. Graden, under G.L.O. contract No. 517, in November, 1884. Surveyors General's notes state: "Set a basalt stone, 13 x 11 x 7 ins., 9 ins. in the ground for corner to secs. 2, 3, 10, and 11, marked with 5 notches on South and 2 notches on East edge. Raised mound of stone alongside."




Description of corner evidence found:

Corner falls on steep hillside. Found definite mound of stone, but no trace of marked stone. May have slid off hill. Used center of mound for corner position.

Description of monument and accessories established to perpetuate the original location of this corner:

At center of above described point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set pipe 4" in the ground to bedrock and mound of stone around to cap.



From which: A 12" fir bears S59°E, 95.8 ft. scribed T3NR40E S11 BT. A 34" pine bears S26°W, 81.3 ft. scribed T3NR40E S10 BT. An 8" fir bears N69°W, 62.0 ft. scribed T3NR40E S3 BT. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Painted blazes red and 6" red band around. Placed 54-4 on steel fence post 5' North of corner.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour
**OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051**

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers
 Robert Stevens
 Ray McVey

July 11, 1979

Office of _____ County Surveyor _____ County of _____ Union _____
 State of _____ Oregon _____, I hereby certify that the within instrument was filed in this office
 for record on the 26 day of _____ July _____, 1979
 _____ by _____
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR	
Date Received _____	
Date Filed _____	
By _____	
File No. <u>196-83R</u>	