


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. F-14

History of original corner establishment:

Not set.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked:  
 Set pipe 15" in the ground to bedrock and mound of stone around to cap.  
 From which: A 14" fir bears S84°E, 25.1 ft. scribed NW 1/16 S10 BT. An 8" fir bears N43°W, 27.4 ft. scribed NW 1/16 S10 BT. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Painted blazes red and 6" red band around. Placed 54-4s on steel fence posts 5' South of and 5' West of corner.

T3NR40E

NW 1/16 — S10

OR PLS 1051  
1979

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers  
Robert Stevens  
Ray McVey

July 12, 1979

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Barry B. Barbour*

OREGON  
OCT. 17, 1973  
BARRY B. BARBOUR  
1051

Office of..... County Surveyor..... County of..... Union

State of..... Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the 26 day of July, 1979

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY  
SURVEYOR**

---

Date Received \_\_\_\_\_

---

Date Filed \_\_\_\_\_

---

By \_\_\_\_\_

---

File No. 198-832