


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. G-14

History of original corner establishment:

Not set.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1 1/4" x 30" galvanized pipe with brass cap marked:
Set pipe 24" in the ground and mound of stone around to cap.

From which: An 11" fir bears S74°W, 57.3 ft. scribed WC 1/16 S10 BT. A 17" fir bears N19°W, 29.9 ft. scribed WC 1/16 S10 BT. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Painted blazes red and 6" red band around. Placed 54-4s on steel fence posts 5' North and 5' East of corner.

T3NR40E
W 1/16



S10
OR PLS 1051
1979

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers
Robert Stevens
Ray McVey

July 12, 1979

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour
OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of.....County Surveyor..... County of..... Union.....
State of.....Oregon..... I hereby certify that the within instrument was filed in this office
for record on the 26 day of July, 1979
..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**
Date Received _____
Date Filed _____
By _____
File No. 201-83R