CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. N-17

History of original corner establishment:

Corner established by H. D. Graden under GLO contract No. 517, in November, 1884. Surveyor General's notes state: "Set a basalt stone 13 x10 x 8 ins. 9 ins. in the ground for cor. to secs. 14, 15, 22, and 23, marked with 3 notches on S. and 2 notches on E. edges. From which: A pine 10ins. diam., bears N52°E, 189 lks. dist., marked T3NR40E S23 BT. A pine, 30 ins. in diam. bears S60°E, 184 lks. dist. marked T3NR40E S23 BT. No other trees within limits; mound of stones alongside."

DIAGRAM
T3NR40E
S15 | S14
S22 | S23

and raised a

Description of corner evidence found:

Found no trace of stone or mound of stone. Corner falls on very steep and eroded hillside. Found 20" pine scribed 3NR40E S14 from which; measured S72°W, 124.7 ft., where the approximate stump hole of a dead and down 36" pine scribed T3NR40E S23 bears S54°E, 121.2 ft. These distances are slope distance. Trees have 54-3 and B.C. location tag on NE BT.

Magnetic variation used: N20°E.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the above described point set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 6" in the ground to bedrock and mound of stone around to cap.

T3NR40E S15 | S14 S22 | S23 OR PLS 1051 1979

From which: A 20" pine bears S74°E, 141.5 ft. scribed T3NR40E S23 BT. A 19" pine bears S77°W, 146.8 ft. scribed T3NR40E S22 BT. No other tree within limits. Placed 54-3 and brass washer stamped PLS 1051 on BTs. Painted blazes red and 6" red band around.

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses:

David L. Landers Daniel T. Rowland

Ray McVey

May 30, 1979

PROFESSIONAL
LAND SURVEYOR

BARRY B. BARBOUR
1 Q \$ 1

Form

Office of County Surveyor Co	1	
for record on the 19th day of June, 1979 (COUNTY OFFICIAL)	, 19	
R6-7100-57 (9/71)	teste Filed	9