


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 3 N R 40 E O-13



DESCRIPTION OF CORNER EVIDENCE FOUND:

Remnants of an ancient North/South fence line falls approx. 12 ft. West of surveyed position.

SEE SURVEY NUMBER 032-2020

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:


At position determined by survey, I set a 5/8" x 30" iron pin, 28" in the ground with 2 1/2" aluminum cap marked as shown with mound of stone 2 ft. base to top of cap, from which:

NEW BEARING OBJECTS:

A 5/8" x 30" iron pin bears South 51°32" West a dist. of 10.60 ft., with 1 1/2" aluminum cap marked SW RP. A 30" Ponderosa Pine bears South 40° East a dist. of 77.20 ft., marked N 1/16 S22 BT.

I hereby certify that the corner was monumented on September 24, 2020.

Witness: Kyle A. Tucker



Renewal Date: June 30, 2021

UNION COUNTY SURVEYOR

Date Received 10/2/20

Date Filed 10/2/20

Filed By MLG/min

File Number 056-2020R

I used a steel tape and magnetic compass in the establishment of the new bearing tree. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing tree. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing tree. A Leica GS18 was used to establish the distance and bearing of the iron pin bearing object. Basis of Bearing is as per Survey 032-2020.