
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Not previously established.

T3N R40 ER-06



DESCRIPTION OF CORNER EVIDENCE FOUND:

None found.

SEE SURVEY 036-2020

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown below and in a 2 ft. diam. collar of stone, From which:

NEW BEARING OBJECTS:

An 11" Ponderosa Pine bears North 7° East a dist. of 50.50 ft., marked W 1/16 S20 BT. A 16" Ponderosa Pine bears South 66° West a dist. of 7.40 ft., marked W 1/16 S29 BT.

Set steel fence post bears North approx. 1'

I hereby certify that the corner was monumented on October 20, 2020.

Witness: Kyle A. Tucker

S20
W 1/16 S29

OPLS 83571
2020

PROFESSIONAL LAND SURVEYOR

REGISTERED

OREGON June 2, 2010 JEFFREY S. HSU 83571

Renewal Date: June 30, 2021

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY
SURVEYOR

Date Received 10/7/76

Date Filed 10/7/70

Filed By 10/7/70

File Number 097 70704