
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Not previously established

T3N R40 ET-02



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 027-2023

## DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown below and in a 1 ft. diam. mound of stone, from which:


## NEW BEARING OBJECTS:

An 11" diam. Ponderosa Pine bears South 84° East, a dist. of 47.90 feet, marked CW 1/16 S30 BT A 10" diam. Ponderosa Pine bears South 9° West, a dist. of 42.80 feet, marked CW 1/16 S30 BT

Set steel fence post approx. 1 feet South

Fence corner falls approx. 30' North and 30' West

I hereby certify that the corner was monumented on October 26, 2023.



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

83571 Renewal Date: June 30, 2025

JEFFREY S. HSU

I used a tape and compass in the establishment of the new accessories. Bearing is measured to a brass washer labeled OPLS 83571 located at the center of BT blaze, with a declination of 14° East. Distance is measured to a 60d spike nailed to the right side base of tree.

UNION COUNTY
SURVEYOR

Data Received 10/30/25

Data Filed 10/30/25

Filed By

File Number 056-2023 P