


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX: U-13

History of original corner establishment:

A. Corner not set by GLO



Description of corner evidence found:

B. MONUMENT FOUND:

none

UNION COUNTY SURVEYOR

Date Received 8-30-89
Date Filed 9-1-89
By G. LANGRITZ, Deputy
File No. 167-89R

Description of monument and accessories established to perpetuate the original location of this corner:

C. I set a 2.5 inch dia. by 30 inch. long aluminum monument 25 inches in the ground. No stones available.

I mark the cap:

T3N R40E WM
S 1/16
S28 + S27
1989

STRYKER PLS 2060

NEW ACCESSORIES ESTABLISHED with magnetic declination of 19 deg. East
15" dia douglas fir bears N60W at 14.8 ft scribed "S 1/16 S28 BT"
19" dia douglas fir bears N78E at 12.2 ft scribed "S 1/16 S27 BT"

Painted red band around each bearing tree.
Placed brass washer marked "PLS 2060" at base of each new BT blaze
Placed LAND SURVEYOR MEMBER LSAW metal signs on each bearing tree
Placed steel fence post at corner.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

REGISTERED PROFESSIONAL LAND SURVEYOR

Edwin A. Stryker
REG. GP# 1989/692-049
OREGON
JULY 15, 1903
EDWIN A. STRYKER
2060